





- Turn the light head clockwise to switch on the light. Turn the light head counter clockwise to switch off the light.

Attention:

- Regularly check condition of sealing O-rings.
- Clean and grease the sealing O-rings every time the light head is removed.

Modes: 100% - 50%

When switching off the light within 5 seconds after it has been switched on, it will pass to the next mode (100%, 50%, 100%, ...) at startup.

If the light remains switched on for more than 5 seconds it'll go to the 100% mode during the next startup.









Handles, umbilicals, ...



Goodman handle, ...



More information on www.green-force.com

Green Force Monostar P4H



Technical data:

Output	
Voltage 4 à 18	
Colour temperature 6.300	K
Beam4	0

Green Force Tristar P4H



Technical data:

Output	
Voltage	
Colour temperature 6.300	
Beam 5	0

Green Force Monostar P7H



Technical data:

Output 900 Power 12	
Voltage 4 à 18	٧
Colour temperature 6.300	
Beam 7	0
Corona	0

Green Force Quadristar XPGH



Technical data:

Output 960 Power 13	
Voltage 4 à 18	٧
Colour temperature 6.300	K
Beam 10 ou 40	0

Green Force Heptastar XPGH



Technical data:

Output	
Voltage 4 à 18	
Colour temperature 6.300	K
Beam10	0